

541 Bukit Batok Street 23, #07-00 Tacam Industrial Building, Singapore 659546 Tel: (65) 6665 7555 Fax: (65) 6665 9555

Fire Door Asset Management

Draft



Tacam Fire Door Asset Management comprises of the following components:

- i) RFID Tag embedded on the metal door panel
- ii) A printed barcode label on Frame (to sync frame with door)
- iii) An Android based Mobile App
- iv) Local / Cloud based Database

The asset management kit is based on android based mobile app that guides the inspectors, installers to automate fire door reporting and adhere to fire door standards SS332:2018 & SCDF Code of practice.




541 Bukit Batok Street 23, #07-00 Tacam Industrial Building, Singapore 659546 Tel: (65) 6665 7555 Fax: (65) 6665 9555

Main Menu (Proposed)

- Lookup by Data Entry or Barcode/ RFID
 Go into Inspection/ check mode by scanning RFID/ Barcode or key in Door ID
- Track multiple Assets
 Asset tracking mode to collect data (eg: Receiving at incoming store/ at installation site..)
- Look up Buildings/ Projects
 Search for data based on project code
- 4. Add Projects / Doors

 Manual key-in or extract from Door schedule
- 5. Offline/ Online
- 6. Sync Data with Server



1. Lookup Mode:

Upon scanning of the RFID tag or Data entry of specific door Following data should appear for inspection purposes

Door ID	
Client	
Project/ Building Name	
Last Inspection Date	
Year of Manufacture	
Frame ID (optional)	
Room Details:	
Room Number	
Level	
Room Name	
Door Number	
Door Details	
Material	
Finish	
Thickness	
Swing	
Door leaf	



541 Bukit Batok Street 23, #07-00 Tacam Industrial Building, Singapore 659546 Tel: (65) 6665 7555 Fax: (65) 6665 9555

т		
Active Door Leaf		
Ratings		
Fire Rating (Hrs)		
Fire Label No.		
Pressure Rating (kPa)		
Sound proofing (STC)		
Dimensions		
Door Width		
Door Height		
Frame Width		
Frame Height		
Vision Panel		
Louvre		
Seals		
	1	
	2	
	3	
Ironmongery		
Hinges	Qty	
	Туре	
Locking system		
	1	
	2	
	3	
Door closer		
	1	
	2	
Door coordinator		









541 Bukit Batok Street 23, #07-00 Tacam Industrial Building, Singapore 659546 Tel: (65) 6665 7555 Fax: (65) 6665 9555

Inspection Mode

FRAME

- ✓ No Loose Frame
- ✓ No damaged Frame
- ✓ No rust through on frames
- √ No missing label
- ✓ Frame is in alignment
- ✓ Correct hardware preparation
- ✓ No improper field modification
- ✓ Any comments _____

PANELS

- ✓ No Damaged Panels
- ✓ No rust through on panels
- √ No missing label
- ✓ Fire label no. is matching
- ✓ Panel is in alignment
- ✓ No improper add-ons to the panel
- ✓ Correct hardware preparation
- ✓ No improper field modification

✓	Any comments	

HARDWARE

Hinges

- ✓ No missing hinges
- √ No loose hinges
- ✓ No missing screws
- ✓ Correct hinges as per database

✓	Any comments	

Door Bolts/ Striker Plates

- ✓ No missing door bolts
- ✓ No missing striker plates
- ✓ Door bolts engage correctly
- ✓ Correct bolts/ striker plates as per database

✓	Any comments	
	•	

Locks

- √ No missing lock
- ✓ No missing screws
- ✓ No missing or lever(s) or Knob(s)



541 Bukit Batok Street 23, #07-00 Tacam Industrial Building, Singapore 659546 Tel: (65) 6665 7555 Fax: (65) 6665 9555

- ✓ No loose lock components
- ✓ Correct locks as per database

v	Others	

Door Closer

- ✓ No missing door closer
- ✓ No leaking door closer
- ✓ No broken arms
- ✓ No missing screws
- ✓ Correct Door closer as per database

✓	Others	


Others

- ✓ No missing door coordinator
- ✓ No missing astragal
- ✓ No missing kickplate
- ✓ No missing door stops
- ✓ No missing thresholds

✓	Others		

OPERATIONAL TEST

- ✓ Door swings freely
- ✓ Door closes properly
- ✓ Door latch secures properly
- ✓ No rubbing against frame
- ✓ Door closer works effectively
- ✓ Door coordinator functions correctly
- ✓ No improper field modification
- ✓ Any comments _____





541 Bukit Batok Street 23, #07-00 Tacam Industrial Building, Singapore 659546 Tel: (65) 6665 7555 Fax: (65) 6665 9555

Compliance Result

	Yes	No
OPERATION TEST	ONAL	
	PASSED	FAIL/ COMMENTS
FRAME	•	
	PASSED	FAIL/ COMMENTS
DOOR	_	
	PASSED	FAIL/ COMMENTS
LOCKS	_	
	PASSED	FAIL/ COMMENTS
HINGES	_	
	PASSED	FAIL/ COMMENTS
DOOR BO	LTS	
	PASSED	FAIL/ COMMENTS
DOOR CL	OSER	
	PASSED	FAIL/ COMMENTS
OTHER		
HARDWA	i -	•
	PASSED	FAIL/ COMMENTS
· ·		
COMMEN	JTS	

Photos







541 Bukit Batok Street 23, #07-00 Tacam Industrial Building, Singapore 659546 Tel: (65) 6665 7555 Fax: (65) 6665 9555

2. Track Multiple Assets

To be used possibly by delivery team in factory, incoming store in Singapore, or Site Supervisor.

- Scan all Frames barcodes
- Scan all panels RFID
- Store data and link to Excel database

3. Lookup Buildings/ Projects

- Search for data based on project code
- Link tags/ Barcodes to database

4. Add Projects

Extract data from Door schedule and populate data in the new project

		F	541 Bukit B	AM STEEL PT atok Street 23, #07-00 Tacam 65 7555 Fax: (65) 6665 9555			546.																				
		Date: 22 .	Jul 2019																								
				DOM DETAILS									DO	OR DET	AILS								HAF	RDWARE	E		
				DOM DE TAILS													-	Ratings									
oc		Room Numbe r	Level	Room Name	Door number	Gridline Location	Categor y	Doo r type	Materi	Finish	Thickn ess	Swin	Activ e door leaf	Door Leaf	DOOR	Fire Ratin g (hour s)	re	proofi	Valu	tiobt	Locking hardware set	Numbe r of hinges	Flush Bolts	Door	Floori doori wall stop	Others	Room Name & numb
		ENTR/ -	GF A																			v					
OC 001	1	01005	Entrance A	SERVICE CORRIDOR 3	01005-B	BEFORE GRIDLINE E/15*16		88	EG	Primer		ООТ	RH	DBL	EDILO	NR	·				EM	10	2 (MAN)	1	4		159
OC 002	2	01005	Entrance A	COOLING TOWER	01005-A	BEFORE GRIDLINE E/13*14	С	B9	EG	Primer		ООТ	LH	SGL	SIRO	NR	-	-		-	EM	8	0	1	2		159
OC 003	3	01007	Entrance A	RAIN WATER COLLECTING ROOM	01007-A	E/14*15		A8	EG	Primer		оит	RH	SGL	SILO	NR	-	\ <u>.</u>		-	CL2	8	0	1(P)	2		159
OC 004	٠	01006	Entrance A	MOBILE GENSET ROOM	01C06-A	BEYOND GRIDLINE F/13*14		A6	SS	Non Direction/H airline (Blook)	1.0	ОПТ	RH	SGL	SIRO	2HRS		-		-	CL2	10	0	1	2		159a
			F	DO CLOCETE				D1								AID					ee						1000

5. Offline/ Online Mode

Offline mode enables technician to conduct most of the operations listed above and then upload to server when there is WiFi/network coverage.

6. Sync Data with Server

Synchronising Data with server may be set to periodic when in online mode, and when moving from offline to online mode.



541 Bukit Batok Street 23, #07-00 Tacam Industrial Building, Singapore 659546 Tel: (65) 6665 7555 Fax: (65) 6665 9555

Revision	Date	Originator	Comments
Draft	03/9/2019	Pradeep Raj	Initial Release
01	15/01/2020	Pradeep Raj	Revised

PROPRIETARY NOTICE

This document and all information contained herein are the property of Tacam Steel Pte Ltd, are provided in confidence, and may not be used, duplicated or disclosed to a third party, in whole or in part, without prior written permission from Tacam Steel Pte Ltd. All rights reserved